


NWT LEGISLATIVE LIBRARY



3 1936 00047 258 7

Fire
Hall
in
Pang.
NWT


JAN 28 1998




CEILING DRYWALL
FALLING & CRACKING




FIRE CHIEF DOOR ①
COMPRESSOR ROOM ②




~~FINDING~~ DRYWALL
CRACKING ON CEILING
STORAGE RM




FLOOR GIVE AWAY
FROM WALLS, 3 1/2"




EXIT DOOR
MAIN BEAM ALL CRACKS




HALL WAY
LOOK AT THE DOORS



MAIN ENTRANCE




MAIN FLOOR ALL
CRACK UP




COMPRESSOR ROOM
OUTSIDE WALL CRACKED




STORAGE ROOM (TOP)




WALL CRACKED
FIRE CHIEF OFFICE




MAIN HALLWAY WALLS
2-3" OFF THE FLOOR




FLOOR 10-12" DROP
ON MAIN HALLWAY




Wall CRACKED
Meeting Room



FIRE CHIEF
DOOR



FLOOR CRACKED



Where Boots ARE 4-5"
Lower than MAIN FLOOR
FLOOR CRACK